

**Appendix B**  
**Photographic Record**





Figure B-1. Killdeer located in Sector 5



Figure B-2. Excavation of the top 6 inches.



Figure B-3. Excavation continued.



Figure B-4. Excavation on the northeast side of CFA-667.



Figure B-5. Excavation continued on northeast side of CFA-667.



Figure B-6. Excavation continued on northeast side of CFA-667.



Figure B-7. Excavation of the southeast side of CFA-667.





Figure B-8. Loading soil for the CFA landfill.



Figure B-9. Roll-off container used for hazardous soils sent off-INEEL.



Figure B-10. Excavation of the northwest side of CFA-677 (Sector 9).



Figure B-11. Excavation of soils to be loaded into soft-sided bags.





Figure B-12. Loading soft-sided bags.



Figure B-13. Moving filled soft-sided bags to temporary storage.




Figure B-14. Composite samples being collected.



Figure B-15. Sample collection continued.



Figure B-16. Sample collection continued.



Figure B-17. Discovery of concrete structure.



Figure B-18. Excavated lid on concrete structure.





Figure B-19. Restoration continued.